Idaho PUC Pipeline Safety Inspection Summary

Inspector(s):	Perkins/Russo		Date(s):	3/7/2019
Company/Owner:	Intermountain Gas Company		Unit/OPID:	Nampa/8160
Inspection Type & Time (1	day, 0.5 day)	-	Total Inspection Days	2
Standard: Construction:	Training:	(T)(D) Integrity Manag	ement: Incident:	
M/M: Follow-up:	2 oq :	Damage Prevention	on: D&A:	
Inspection Summary				
Audit consisted of onsite foll Shutdown (LES) federal repo		the IGC LNG plant in	Nampa, following the Li	quid Emergency
7 March 2019: (2 Follow-up)				
A follow-up inspection was conducted by the Idaho Public Utilities Commission's Pipeline Safety Division on Intermountain Gas Companies LNG Plant in Nampa following the Liquid Emergency Shutdown. Typed report.				
Attachments: IGC's written notification Misc. photos				
Corrective Action Required:		w-up Required:	Yes No	Х
Inspector (Lead): Bruce Perkins	Ar a fash		by (date): Date:	7 MGR 19
Reviewer:	h. Cor	HALA	Date:	